



Installing SOLOdrive 1060/A, 1061/A



A Removing the covers





B Removing the strain reliefs





C Mounting the SOLOdrive

In Europe, use a H03V 0.75mm² power cable and apply following strip lengths:



Pay attention when connecting the LED groups:

- polarity reversal results in no light output and often damages the LEDs
- combining + and - of different groups damages the driver



D Making the wire connections



E Fastening the strain reliefs



F Replacing the covers



WARNING: Risk of electrical shock. May result in serious injury or death. Disconnect power before servicing or installing.



CAUTION: The device may only be connected and installed by a qualified electrician. All applicable regulations, legislation and building codes must be observed. Incorrect installation of the device can cause irreparable damage to the device and the connected LEDs.